

15th December 1959]

## APPENDIX I.

[Vide answer to starred question No. 186 asked by Sri R. Srinivasa Iyer at the meeting of the Legislative Assembly held on 15th December 1959, page 127 supra.]

The particulars of materials obtained after dismantling the buildings that were demobilized for the construction of the Women Students' Hostel are given below :—

Serial number.	Quantity.	Description of material.
<i>List of materials obtained after dismantling the existing garages, stores in the compound.</i>		
1	2,477 c.ft. . . . .	Brick.
2	1,022 c.ft. . . . .	Flooring concrete.
3	3,100 Nos. . . . .	Flat tiles.
4	2 Nos. . . . .	Door D. 3' 6" × 6' 6".
5	2 „ . . . . .	Door D. 8' 0" × 9' 6".
6	7 „ . . . . .	Window W. 4' 0" × 5' 0".
7	4 „ . . . . .	Ventilator 4' 0" × 2' 0"
8	1 No. . . . .	Almyrah 3' 6" × 4' 6".
9	1 „ . . . . .	Partition with expanded metal with under frame— (a) 18' 0" × 10' 0". (b) 18' 0" × 4' 3" 2
10	129 c.ft. . . . .	Wall plate 4" × 3".
11	64' 6" . . . . .	Ridge Piece 4" × 9".
12	58 Nos. . . . .	Rafters 14' 0" × 4" × 2".
13	64 Nos. × 28" and 14 Nos. × 28" . . . . .	Reepers 2" × ½".
14	1,533+1,171 Nos. . . . .	Mangalore tiles (including dama ones).
<i>Materials obtained from dismantling the existing building occupied by the Inspector of Fisheries.</i>		
1	5,790 } 1,459 } c.ft. . . . .	Brick debris.
		Doors—
2	1 No. . . . .	4' 0" × 6' 6".
	12 Nos. . . . .	3' 0" × 6' 6".
	3 „ . . . . .	3' 0" × 6' 6".
	1 No. . . . .	4' 0" × 7' 0".
	1 „ . . . . .	4' 0" × 7' 6".
	1 „ . . . . .	2' 6" × 6' 0".
	1 „ . . . . .	4' 6" × 7' 0".
		Windows—
	9 Nos. . . . .	4' 0" × 5' 0".
	6 „ . . . . .	3' 0" × 5' 0".
	3 „ . . . . .	2' 0" × 3' 0".
	2 „ . . . . .	3' 0" × 4' 0".
3	6,314 c.ft. . . . .	Teakwood.
4	1,756 „ . . . . .	Roof of concrete.
5	950 „ . . . . .	Floor concrete.
6	1,425 Nos. . . . .	Mangalore tiles.



[15th December 1959]

*Materials obtained after dismantling the existing building  
occupied by the Director of Animal Husbandry.*

<i>Serial number.</i>	<i>Quantity.</i>	<i>Description of material.</i>
1	17,627 c.ft. .. ..	Brick debris.
2	1,680 „ .. ..	Flooring concrete.
3	2,642 „ .. ..	Roofing concrete.
4	1,564 Nos. .. ..	Roofing flat tiles.
5	7,044 c.ft. .. ..	Basement concrete.
6	119.75 „ .. ..	Cut stones.
		Windows—
7	4 Nos. .. ..	1' 10½" × 3' 0".
	4 „ .. ..	2' 0" × 3' 0".
	12 „ .. ..	4' 6" × 10' 0".
	1 No. .. ..	5' 6" × 10' 0".
		Doors—
8	5 Nos. .. ..	2' 0" × 7' 0".
	16 „ .. ..	4' 6" × 12' 6".
	6 „ .. ..	3' 0" × 6' 0".
	1 No. .. ..	2' 6" × 7' 0".
	1 „ .. ..	3' 0" × 8' 0".
	1 „ .. ..	3' 0" × 6' 6".
	2 Nos. .. ..	3' 0" × 6' 0".
		Glazed window shutter only—
9	4 „ .. ..	3' 6" × 2' 6".
	4 „ .. ..	2' 6" × 3' 0".
	4 „ .. ..	4' 6" × 2' 6".
	4 „ .. ..	1' 3" × 3' 0".
	4 „ .. ..	3' 1½" × 3' 6".
	4 „ .. ..	6' 4" × 3' 6".
	8 „ .. ..	4' 4" × 3' 1".
	8 „ .. ..	4' 2½" × 3' 4".
	4 „ .. ..	3' 0" × 3' 3".
	4 „ .. ..	2' 6" × 3' 3".
	8 „ .. ..	1' 0" × 3' 4".
	4 „ .. ..	1' 3" × 3' 0".
10	1,551 sq. ft. (including broken slab) .. ..	Cuddapah slab.
11	20,160 Nos. (including broken tiles) .. ..	Flooring tiles.
12	432 c.ft. .. ..	Old Teakwood.
13	1 No. .. ..	2' 0" M.S. angle.
14	2 Nos. .. ..	Wash handbasin.
		33' 0" × 1' 6" × 0' 7".
	12 „ .. ..	17' 0" × 1' 0" × 0' 5".
16	4,156 Nos. (including broken tiles) .. ..	Mangalore tiles.
17	1 No. (in five pieces) ..	Partition—
		14' 9" × 12' 3".
		17' 9" × 17' 3".
		End walls of room with—
18	4 Nos. (in five pieces) ..	6' 0" × 10' 0".
	4 Nos. (in five pieces) ..	6' 2" 5' 0".